

DELHI JAL BOARD (Govt of NCT of Delhi)
ZONAL QUALITY CONTROL LABORATORY (SOUTH)
WATER WORKS, OKHLA, NEW DELHI-110025

No. DJB/DTQC/ CWA (C) / ACWA (south)/ Paid/ Bact. / 2021-2022 / 115-116/09.02.2022 dated:.....

Bacteriological Analysis Report as per IS 10500:2012

To M/s G.L.T Saraswati Bai Party Ref.No./Date : G.L.T.S.B.M./Nehru Nagar,
Mandir, Sr. Sec. School 1619/28.12.2021
Nehru Nagar, Ring Road Deptt.Challan No. /date: 222/30.12.2021
New Delhi-110065 Dt. of sample collection: 03.2.2022
No. of Sample: Two (02)
Collected by: Name- Sh. V.P Singh
Desig.- Bacteriologist.

Sr.No. as in record book	Particulars	Clarity	Residual chlorine	Total coliform/ E.coli in 100 ml sample
1.	UGT Near Main Gate at above school.	Clean	1.0	0
2.	Tap Drinking point Gr. Floor.	Clean	Nil	0

RESULT: ✓ Collected water sample(s) as mentioned above at Sr.No. 1, 2 was/ were found bacteriological satisfactory, hence the water/source is fit for drinking/recreational purpose subject to satisfactory attached Physical-Chemical Analysis report also.

✗ Collected water sample(s) as mentioned above at Sr.No. ✗ was/ were found bacteriological unsatisfactory, hence it is advised that the water/source may not be fit for drinking/recreational purpose as such.

f. Shankar
Asstt. Bact.
4.03.22

[Signature]
Bacteriologist (South)
04/03/2022

[Signature]
ACWA (South)
04/03/22

DELHI JAL BOARD (Govt of NCT of Delhi)
 ZONAL QUALITY CONTROL LABORATORY (SOUTH)
 WATER WORKS, OKHLA, NEW DELHI-110025

No. DJB/DTQC/ CWA (C) / ACWA (south)/ Paid/ Bact. / 2021-2022/115-116/09.02.2022 Dated:.....

Bacteriological Analysis Report as per IS 10500:2012

To M/s G.L.T Saraswati Bai
 Mandir, Sr. Sec. School
 Nehru Nagan, Ring Road
 New Delhi-110065

Party Ref.No./Date : G.L.T.S.B.M./Nehru(Nagan)/
 1619/28.12.2021
 Deptt.Challan No. /date: 222/30.12.2021
 Dt.of sample collection: 03.2.2022
 No. of Sample: Two (02)
 Collected by: Name- Sh. V.P Singh
 Desig.- Bacteriologist.

Sr.No. as in record book	Particulars	Clarity	Residual chlorine	Total coliform/ E.coli in 100 ml sample
1.	UGT Near Main Gate at above school.	Clear	1.0	0
2.	Tap Drinking point Gr. Floor.	Clear	Nil	0

RESULT: Collected water sample(s) as mentioned above at Sr.No. 1,2 was/ were found bacteriological satisfactory, hence the water/source is fit for drinking/recreational purpose subject to satisfactory attached Physical-Chemical Analysis report also.

Collected water sample(s) as mentioned above at Sr.No. X was/ were found bacteriological unsatisfactory, hence it is advised that the water/source may not be fit for drinking/recreational purpose as such.

f. Shankar
 04.03.22
 Asstt. Bact.

[Signature]
 04/03/2022
 Bacteriologist (South)

[Signature]
 04/03/22
 ACWA (South)